

## DIY tool to remove wire socket terminal from a Terratrip 202+ or 303+ 12 pin plug



To remove a socket terminal from the 12 pin plug, insert the tool into the correct location in the 12 pin plug, from the end that fits into the Terratrip, twisting slightly as you gently push in the tool. The tool should go in about 11 mm and firmly stop. At this point, then gently pull the socket terminal out by pulling on the wire at the other end of the hole. If you crimped your terminal and did not solder it, you might find that only the wire comes out. Can't help you there, unless you cut about 50mm of the 5/32" tube, omit fitting the handle, push the bare tube into the correct hole, then slide a longer piece of 1/8" brass tube down the centre of the 5/32" tube, and push out the terminal.